Approved For Release 2001/05/11 : CIA-RDP78B04747A001400030023-9

99730-4

NPIC/P&DS/D/6-1421
15 June 1966

MEMORANDUM FOR THE RECORD

SUBJECT: [redacted] Light Table # 2 Deficiencies

1. Front shade does not function (washers were added to raise the top casting from its base but this reduced the microscope transport carriage's clearence). Cover glass can now not be installed. Spacers (washers) must be removed and another "fix" for the shade found.

2. A set screw for the left front solenoid on the tensioning mechanism is missing.

STATINTL 3. The front brake on the microscope carriage does not function.

4. The glass cover plate must be properly installed.

STATINTL 5. [redacted] will fix during week of 13 June 1966 at this facility.

STATINTL [redacted]
Development Branch, P&DS

Distribution:
Orig - Project File (99730-4)
2 - DB/ISS Chronos

pnf

DECLASS REVIEW BY NIMA / DoD

Approved For Release 2001/05/11 : CIA-RDP78B04747A001400030023-9